



HDD-272, Phase III - Near JP Chowk  
Ring Road No.-2, Kabir Nagar, Raipur (C.G.) - 492099  
Ph : 0771 - 4027777 | Email : ultimatenviron@gmail.com

Recognized by Ministry of Environment Forest and Climate Change under EP act 1996

|   |                                   |                          |  |
|---|-----------------------------------|--------------------------|--|
| <i>Name &amp; Address Of The Customer</i>   |                                   | REPORT NO                | UES/TR/22-23/05365                           |
| <b>To,<br/>SHRI BAJRANG POWER &amp; ISPAT LTD.<br/>VILL: TANDAWA &amp; KUNDRU,<br/>DHARSIWA -TILDA ROAD ,<br/>TEHSIL -TILDA, RAIPUR(C.G.)</b> |                                   | LAB REF NO               | UES/22-23/N/012061-012066                    |
|   |                                   | DATE OF SAMPLING         | 10/11/2022 to 11/11/2022                     |
|   |                                   | DATE OF REPORT           | 15/11/2022                                   |
|   |                                   | <b>SAMPLE DETAILS</b>    |  |
| MONITORING FOR  | NOISE LEVEL MONITORING            | CUSTOMER REF. NO. & DATE | SBPIL/TILDA/ENV/2022-23/1404, DTD.22/10/2022 |
| SAMPLING LOCATION   | INSIDE PLANT (AS DESCRIBED BELOW) |                          |  |
| SAMPLE RECEIVED ON  | MONITORING AT                     | SAMPLE COLLECTED BY      | LABORATORY CHEMIST                           |
| SAMPLING PROCEDURE  | MANUFACTURER'S INSTRUCTION        |                          |  |
| SAMPLE QUANTITY/PACKING   | NOT APPLICABLE                    |                          |  |

| <b>TEST REPORT</b>             |        |          |            |                         |            |
|--------------------------------|--------|----------|------------|-------------------------|------------|
| LOCATION                       | UNIT   | RESULT   |            | LIMIT (INDUSTRIAL ZONE) |            |
|                                |        | DAY TIME | NIGHT TIME | DAY TIME                | NIGHT TIME |
| NEAR SID COOLER DISCHARGE AREA | dB (A) | 71       | 63         | 75                      | 70         |
| NEAR RAW MATERIAL YARD         | dB (A) | 67       | 47         |                         |            |
| NEAR POWER PLANT               | dB (A) | 63       | 54         |                         |            |
| NEAR MAIN GATE                 | dB (A) | 68       | 51         |                         |            |
| NEAR PALLET PLANT              | dB (A) | 65       | 56         |                         |            |
| NEAR BANIFICATION PLANT        | dB (A) | 67       | 59         |                         |            |

**REMARKS: RESULTS ARE AS ABOVE**

**Terms & conditions**

- The report for publication, arbitration or as legal dispute is forbidden.
- Test sample will be retained for 15 days after issue of test report unless otherwise agreed with customer.
- This is for information as the party has asked for above test(s) only

|                                      |                                   |   |
|--------------------------------------|-----------------------------------|---|
| <br>15/11/2022<br><b>PREPARED BY</b> | <br><b>End of the test report</b> | For ULTIMATE ENVIROLYTICAL SOLUTIONS<br><br><b>AUTHORIZED SIGNATORY</b> |
|--------------------------------------|-----------------------------------|---|